



DEPARTMENT OF  
WATER RESOURCES

# BUTTE CREEK *Fact Sheet*

PL84-99 Sites

## Emergency Levee Repairs

### Location

River: Butte Creek

Site Identification #:

20051230-034-003

(Levee Mile 2.08)

Latitude/Longitude:

39.670530/-121.781500

Nearest Impact Area:

Agricultural/Residential

County: Butte

Bank: Left

### Type of Damage

Bank erosion

### Total Length of Repair


340 feet (approximate)

### Repair Type

Rock slope protection,  
rock-soil fill

### Lead Agency

Maintenance Area 5



For further information,  
please contact:

Elizabeth Scott  
DWR Public Affairs Office  
(916) 835-5344  
[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

[www.levees.water.ca.gov](http://www.levees.water.ca.gov)